ATTACHMENT G

MATERIAL SAFETY DATA SHEET



USG INTERIORS, INC. 101 S. Wacker Drive Chicago, IL 60606-4385

Emergency phone: Day 312/606-3759

Night 312/606-4382

Oate Issued:

Harry Wall Strain Control

November 16, 1990

SECTION I

A STATE OF THE STA	The second second	THE REPORT OF THE PARTY OF THE	200	Cristian Pro-
CONTRACTOR OF THE PARTY OF THE				The second second
* RKLOVS	A 488 B 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4	9 - 20 - 20 - 20 - 20 - 20 - 20 - 20 - 2	20.00	8 4 2 2 2
A PROPERTY OF THE PARTY OF THE		ALC: NO PERSONAL PROPERTY.		market was a second
	the same of the same of		44.0	4. 4. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1.

(Chia 19an A-14a), was can canadant, dada Hanton anasasa ngambang masaboy (Panada Panada

PATERIAL			PEL	\$ 5,40
Mineral Fiber *	60-80	10 mg/7t ³	15 mg/14 ³	(ŃE)
Perlite	10-20	10 mg/M ³	15 mg/H ³	93763_70_3
Starch	S-10	la mg/H ₃	15 mg/H ³	09005-25-8
Cellulose	10~20	10 mg/M ³	15 mg/H ³	09005-34-6
-Silica Sand+	. 0-2	0.1 mg/H ³ (R)	$0.1 \log/H^3$ (R)	14808-60-7
(* trace quantity)		• •		

- WHMIS Class D2B (R) - Respirable (NE) - Not Established

SECTION III
PHYSICAL DATA

DENSITY:

APPEARANCE AND ODOR:

16-20 pcf ...

Tan-colored board, low cdcr.

SECTION IY FIRE AND EXPLOSION HAZARD DATA

SPECIAL FIRE FIGHTING PROCEDURES: None, Fire hazard Classification per ASTM E-84; Fiame Spread 25, Smoke Developed 5.
UNUSUAL FIRE OR EXPLOSION HAZAROS: None known.

SECTION V

EFFECTS OF GRADUSCHISTORS

ACEPTE TERM FROM AND MENDER WAS EDUCE FORESTAND AND ACTION OF THE PROPERTY OF THE PARTY OF THE ACTION OF THE P CHIEFEON OF FROM TO EDUCATION A SOCIETY OF THE OPEN AND ACTION OF THE PARTY OF THE ACTION OF THE ACTION

Theoretic contensions of the carried library conjugations of another districts from the contension of the carried library confidence of an array of the carried library carrie

Therefore the extension of each or the expension to enter the figure there are alreading to the continues to the decimal of a continues to the decimal of the continues to the decimal of the decimal of

Case 1:05-cv-00160-SJM-SPB Document 17-8 Filed 03/23/2006 Page 3 of 4
The scientists reporting these results and independent scientists reviewing these
results agree that further study is necessary to determine what other factors might
be responsible for this reported increased risk. Further studies are now being
conducted to investigate what effects other occupational exposures and life-style had
on these workers. The records will also be examined to learn if these workers had
exposure to other known carcinogens in the past.

Several research studies using animals have shown that breathing of airborne mineral wool fiber does not cause any lung cancer or other lung diseases.

CARCINOGENIC CLASSIFICATION:

Silica (respirable)

- LARC-2A, NTP-None, OSHA-None

Man-made vitreous fiber (respirable)

- LARC-2B, NTP-None, OSHA-None

EMERGENCY AND FIRST ALD PROCEDURES:

EYES: flush thoroughly with water. If irritation continues, see physician.

SKIN: Wash skin after exposure.

INGESTION: Call PHYSICIAN

SECTION VI REACTIVITY DATA

STABILITY:

HAZARDOUS POLYMERIZATION:

Stable Will not occur.

SECTION VII SPILL OR LEAK PROCEDURES



STEPS TO BE TAKEN IN CASE MATERIAL IS RELEASED OR SPILLED: Normal cleanup redures.' Avoid creating dust.

WASTE FISAL METHOD: To landfill in accordance with local, state and federal

SECTION VILI SPECIAL PROTECTION INFORMATION

RESPIRATORY PROTECTION: NIOSH approved respirator.

VENTILATION: Local exhaust or mechanical ventilation to keep below TLY.
PROTECTIVE EQUIPMENT: Protective gloves and goggles are recommended. Wear

loose-fittir -lothing closed at the neck and wrists and minimize skin exposure.

Wash work is separately. Rinse washer thoroughly after use.

SECTION IX SPECIAL PRECAUTIONS

PRECAUTIONS TO BE TAKEN IN HANDLING AND STORING: Store in a dry place. When cutting or breaking, avoid creating excessive dust.

OTHER PRECAUTIONS: During the initial firing of a vessel insulated with this product, if the insulations temperature exceeds approximately 450° F the combustion products of a paper fire will be emitted. If the initial firing or curing is done in an oxygen deficient atmosphere, carbon monoxide and Aldehydes are likely to be produced. Therefore the adjacent area must be well ventilated.



For further technical information contact:

technical fanager, dept. 410, USG INTERIORS, INC., 101 South Wacker Drive, Chicago, to 60506-1385, Priores, (312) 606-4382






This Material Handling sheet is to inform both staff and immates of the proper equipment to be used in handling material safely. Below is a list of the safety equipment which is available through staff. Those items that are marked with an X MUST be used for safe handling of this particular material.

The Health, Flammability & Reactivity chart reflects this products

hazards by using the numbers 0 - 4.





Manejo de Material v Informaccion de Proteccion Personal

e de Producto: U.S.G. INTERIORS MICORE BOARD

Esta hoja de Manejo de Material es para informar a el staff y el personal, sobre el uso adecuado del equipo a utilizar en el seguro manejo del material.

Abajo esta la lista del equipo de seguridad disponiblé por el staff. Los articulos marcados con una X DEEEN ser utilizados par el seguro uso del material específico.

Il cuadro de Salud, Flamibilidad y Reactividad ensena los peligros de este producto, usando los numeros del 0 - 4.

